

02/05/26 mbrxigrt61037_35.ppp_defaut-4644d-15_7-stp

732671 s: Mdev= 0.29200E-11 Tdev= 1235200 ps
 366336 s: Mdev= 0.17644E-11 Tdev= 373170 ps
 183168 s: Mdev= 0.17192E-11 Tdev= 181800 ps
 91584 s: Mdev= 0.28560E-11 Tdev= 151020 ps
 45792 s: Mdev= 0.39954E-11 Tdev= 105630 ps
 22896 s: Mdev= 0.55021E-11 Tdev= 72732 ps
 11448 s: Mdev= 0.77742E-11 Tdev= 51383 ps
 5724 s: Mdev= 0.10979E-10 Tdev= 36282 ps
 2862 s: Mdev= 0.15588E-10 Tdev= 25757 ps
 1431 s: Mdev= 0.22532E-10 Tdev= 18616 ps
 716 s: Mdev= 0.34556E-10 Tdev= 14275 ps
 358 s: Mdev= 0.61888E-10 Tdev= 12783 ps

Following steps removed:

61037.26563 : Step 1 -100 ns
 61038.25868 : Step 2 -100 ns
 61044.09896 : Step 3 -100 ns
 61056.49826 : Step 4 2600 ns
 61059.28819 : Step 5 2600 ns
 61061.47049 : Step 6 -100 ns
 61068.47049 : Step 7 -100 ns

